Calibration curves for the quantitation of metal concentration



a. Regression of iron



b. Regression of zinc



c. regression of copper



d. Regression of cadmium



e. Regression of cobalt



f. Regression of chromium



g. Regression of lead



h. Regression of nickel