

Highlights:

- Process-induced defects in the 3D-printed polymeric lattice were investigated.
- Geometry-related defects and internal voids were types of imperfections detected.
- A novel method to capture the morphology and distribution of voids was proposed.
- The geometry of voids suggests the lack of fusion as the origin of void formation.